

TRIP REPORT TDEC – DIVISION OF WATER POLLUTION CONTROL COOKEVILLE ENVIRONMENTAL FIELD OFFICE			
Date	2 January 2010	File No.	SOP-09025
Site Name	Watson Farm	Investigator	JEHa
Site Address	230 Old Watson Road	Signature	<i>James Hartman</i>
Site Contact(s)	Jerry Watson	Other Personnel	N/A
Site Phone	931-243-3173	Stream	unnamed tributary to Cumberland River
Other Phone(s)	N/A	Pollutant	Ag/Animal Waste
County	Clay	Drainage	Cumberland River
Town / City	Celina	Weather	Rain
Latitude	36.566700	Photos Taken?	Yes
Longitude	-85.511300	Samples Taken?	No

Purpose of Visit

Compliance Inspection

Report & Recommendation

No water quality issues were noted at the site. Litter building is less than 25% full. No litter is outside and gravel lot was clean. Storm water is routed to the rear of the facility. Litter and soil analysis are kept up to date. Facility is now under an SOP.